




DIENST

Start of the Shift

103178

End of the Shift

103179

Start of Assessments

103180

End of Assessments

103181


Travel Time To

103271

Travel Time From

103272

KAMERS

Scania 123

103182

Scania 124

103194

Scania 125

103195

Scania 126

103196

Scania 127

103197

Zhongtong 128

103198

Zhongtong 129

103199

Zhongtong 130

103200

Zhongtong 131

103201

Zhongtong 132

103202

Hino 133

103203

Hino 134

103204

Hino 135

103205

Hino 136

103206

Hino 137

103207

Zhongtong 138

103211

Zhongtong 139

103212

Zhongtong 140

103213

Zhongtong 141

103214

Zhongtong 142

103215

MB 1632

103222

TJ 232

103223

TJ 499


103224

TJ 0148

103225

TJ 128

103226

PDD 466

103227

Nr. 7

103228

Halte Slipi

103268

Halte Dukuh Atas 1



103270

Halte Semayang JCC



103273

Halte Bendungan Uilir



103274

Halte Polta



103275

PROGRAMMA'S

Daily Cleaning Interi...



103183

Periodical Cleaning I...



103184

Daily Washing Outside



103185

Periodical Waxing B...



103186

Graffiti Removing In...



103187

Check Tire Pressure ...



103188

Check Lightning Syst...



103189

Quick Engine Check



103190

Replace Window




103191

Changing Tire




103192

Refueling




103193

Oil & Water Check




103216

Daily Halte Cleaning



103269


Halte Periodical Cle...



103276


ACTIVITEITEN

Brake Pressure Insuf...




103145

Direction Light Brok...




103146

Display Not Working




103147

Front Lighting Left B...




103148

Front Lighting Right ...




103149

Rear Lighting Left Br...




103150

Rear Lighting Right ...




103151

Hazard Lighting Bro...




103152

Kit Incomplete




103153

Seating Broken




103154

Tire Pressure Insuffi...




103155

Window Glass Broken




103156


Wipers Malfunction




Mirror Leftside Broken



Mirror Rightside Bro...



Floor Dusty




103157

103158

103159


103160

Floor Attached Dirt




103161

Graffiti on Interior




103162

Graffiti on Exterior




103163

Handles Attached Dirt




103164

Seatings Attached Di...




103165

Window Interior Dirty




103166

Inner Walls Attache...




103167

Doors Inside Attache...




103168

Waste Bins Full




103277

Metal Wall Attached...




103278

Ceilings Attached Dirt




103279

Glass Doors Fingerpr...



103280


Separation Glass Att...



103281


WAARDERING

Excellent




103173

Very Good




103174

Sufficient




103175

Insufficient




103176

Not Rated



103177

Good



103221